

# Check

## Vehicle Information

Make	Perodua
Model	Bezza
Year	2016
Color	

Print Report

**Black**

Mileage

**203,220**

Transmission

**Automatic**

License Plate

**RP1681**

## Overall Rating

Vehicle Condition

**Good**

## Vehicle Photos



Front View

**Print Report**

Recommended  
Side Structure

Title & student info
Background / problem statement
Research gap
Objectives / research questions
Methodology
Results
Discussion
Conclusion
Limitations & future work
👉 Typically 10–12 slides only

Rear View

Inspection Checklist

Item	Rating
Exterior Body Condition	Good
Glass & Windows	Good
Engine Performance	Good

Additional Notes

All ok. body paint a little bit need to repair

This report was generated by AutoCheck Pro on January 30, 2026 at 12:12 PM

Report ID: RPT-20260130-206425

Print Report